Subject: Re: FRS Calibration Issue

Posted by SMilne on Wed, 17 Sep 2014 14:01:19 GMT

View Forum Message <> Reply to Message

Hi Liliana,

I was not aware Z_in was referring to Z of element of calibration. I've changed that now.

Yeah, I was using the correct magnetic fields when producing the 46Ti spectrum.

Well, I've used the correct magnetic field settings for each of the 58Ni calibration runs and as you can imagine the result is not what we want, but at least they are consistently wrong. Do you have the program gnumeric? I can show in there my calibration steps, tables and graphs.


(Also, when I refer to calibration steps 'working' by this I mean I get my measured betas and TOF values matching near perfectly to the LISE files, i.e. my measured beta values are within ~0.05% of LISE values.)

Thanks, Scott


File Attachments

1) 58Ni-Call.png, downloaded 1042 times

⁵⁸Ni Calibration Point



⁵⁸Ni Calibration Point 2



⁵⁸Ni Calibration Point

