
Subject: Re: segmentation violation in sim macro
Posted by [Albrecht Gillitzer](#) on Mon, 16 Apr 2012 15:19:37 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hello Ralf,

Thank you for this clarification. Clearly, there is no active detector at this (and even beyond this) point.

It seems this coordinate (18.3,-71.5,-150.0) is just at the border of two elements (ms01_0, ms04_0) of the solenoid backward endcap. This I saw with help of Tobias looking at the geometry in the Event Display. I didn't see the DIRC there.

Can anybody (who feels competent and responsible to do this) check whether or not the geometry is correctly implemented, and eventually correct it if necessary?

Best regards,
Albrecht
