Subject: Re: Field cage resistor chain location
Posted by fateev on Tue, 30 Nov 2004 10:50:54 GMT
View Forum Message <> Reply to Message

Hello,
we solder the resistors on anode side.
ground from last resistor comes out next to anode side.
look at a drawing

cheers,
Oleg

File Attachments

1) ground drift HV.bmp, downloaded 1007 times