I should mention, that all these corrections should be done after the calibration of the PMTs is already optimized.
Calibrated PMTs will already give a good x:y pattern. The offset, rotation, and shear corrections are for fine-tuning the result.