

---

Subject: Re: Drift HV to Radiator connection

Posted by [Clemens Adler](#) on Mon, 06 Dec 2004 13:58:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello Oleg,

according to Hannes the Radiator surface should still be gas tight even with some scratches. He gave a piece of Radiator which was already a bit damaged (little scratches, as far as I know) to GSI (some year ago) and they tested it and it was still gas tight. Maybe he can comment about this.

cheers,  
Clemens

---