

---

Subject: Glue Aw 106 and Aw116 with Hardener HV 953 U  
Posted by [Joerg Hehner](#) on Mon, 06 Jun 2005 08:52:37 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Dear Chamberbuilders,

we encountered a problem related to the HV 953 U hardener:  
After curing of the glue (AW 106/116 mixed with the hardener)  
the surface of the cured glue feels sticky and humid. First  
we thought that this might be related to the humidity, since  
the stiffness/solidity was OK. Testing of the chambers also  
did not show increased currents. However, we did contact the  
supply company and they admitted problems with the hardener  
since the end of last year (they changed their supply source).  
The specified characteristics of the glue (hardener) might thus  
not be guaranteed any more. Consequently we need to know:

- 1) Do you also observe the same features (stickiness of the  
surface of the glue after curing)?
- 2) What are the "Ident-Numbers" and "Batch-Numbers" of the  
hardener and glue cans that you received. They are indicated  
on the labels of the cans. They are for example (one of our  
cans): Ident Number 041221400 and Batch Number AD41005300.  
Please send these numbers to me (Joerg) as fast as possible.

Best regards,  
Joerg and Christian

---