Subject: Re: FRS Calibration Issue Posted by SMilne on Tue, 17 Feb 2015 16:20:40 GMT

View Forum Message <> Reply to Message

Hi Liliana,

So I tried your updated processor and this is what I received for the diff_visu left and right. So, the left certainly changes with some peak structure close to 0, however the right seems pretty much the same.

Any ideas?

Thanks again, Scott


File Attachments

1) diff_visu-Left.png, downloaded 387 times

Page 1 of 3 ---- Generated from

GSI Forum

diff_visu_Tof_Left



2) diff_visu-Right.png, downloaded 384 times

diff_visu_Tof_Right

