Subject: Re: Drift HV to Radiator connection Posted by Harald Appelshaeuser on Thu, 23 Sep 2004 09:36:19 GMT View Forum Message <> Reply to Message

Hi Clemens,

- 1. indeed this shielding is a tricky thing. we fell into the same trap with the very first proto we built in hd (sorry that i didnt communicate this well enough)
- 2. it seems to me that this copper strip is a weak point in the design. i dont see a problem with tiny drops of epoxy to improve the stability but maybe somebody has a good idea for a more reliable solution?

Harry

Page 1 of 1 ---- Generated from GSI Forum