Subject: Re: Drift HV to Radiator connection Posted by Clemens Adler on Tue, 25 Jan 2005 16:06:31 GMT View Forum Message <> Reply to Message

Hi Chilo,

The only red glue we use is Technicoll 8266/67 which is used for glueing the wires onto the wiring frame. Is there a Problem with that?

Concerning the shocks you got, I'm a bit surprised, I never experienced anything like this. In principle there is (should be) 5 cm of highly isolating material between the drift cathode and the outer surface. I don't know whether there is any likelyhood of this thing charging up over some time. The only thing I could imagine is that maybe somehow the glue would contain too much humidity to allow leak currents, but this would be very unlikely over this distance... In any case, it will not hurt to put a piece of this 3M copper shielding tape to ground this side.

cheers, Clemens

Page 1 of 1 ---- Generated from GSI Forum