
Subject: [FIXED] Beam pipe valves?

Posted by [Stefano Spataro](#) on Tue, 05 Mar 2013 11:09:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

Dear all,
today I plotted the PANDA geometry and I have seen something strange:

In the OGL drawing you can see that the pipe has a sort of "tower" which is in the middle of the muon filter. I am wondering what is wrong there, if the "tower" should be really there, if maybe the muon filter should be modified to host it, or if maybe we have some geometry problems.

Waiting for the experts' comments...

File Attachments

1) [viewer.gif](#), downloaded 458 times

