
Subject: Re: FRS - TPC Calibrations

Posted by [mlcortes](#) on Thu, 04 Jun 2015 07:27:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi Tayfun,

It looks like a weird problem.

To which data correspond the plots you sent (is it a primary beam and how long after the calibration runs?)?

If the new_prespec_Go4 plot is for the same data that the prespec code, can you please give them the same binning?

And also, can you please plot separately xc and yc. If you put them in a 2D plot they are plotted all vs all and then we cannot see if one of them is not fine. A plot with the supersposition of all xc and another plot wit all yc can possibly give us a hint.

So you say that in any case, the calibration that you make in the new_prespec_Go4 does not work for the experimental data inside the same code?

So it means that the calibration changed at some point. Have you checked when does this happen? Is it a clear difference or the first files are still working with the calibration?

About the prespec code, what do you mean by not being able to replay the mask files? Do you get an error message? Did you check that you have the correct channel for the mask input?

If you tell me the file name of the calibration mask at S4 I can run it with prespec code to try to understand what happens.

Liliana
