Subject: Re: Problems with new GEM Geometry Posted by StefanoSpataro on Tue, 17 Apr 2018 09:28:43 GMT View Forum Message <> Reply to Message

Something similar happened several years ago, when the geometry of one GEM plane was shifted a bit, and the corresponding recohits were not properly updated (and the Kalman was not able to fit such wrongly placed hits).

Page 1 of 1 ---- Generated from GSI Forum