
Subject: Re: Issues on the mvd root geometry 1.0
Posted by [Stefano Spataro](#) on Thu, 03 Apr 2008 16:38:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

The beampipe geometry was just converted from the step file of the old framework. So it can be that it is not updated, and that is maybe the reason of the overlaps.
