Subject: Re: Problems with MVD geometries Posted by Tobias Stockmanns on Tue, 12 May 2009 07:47:50 GMT View Forum Message <> Reply to Message

Dear Ralf and Simone,

can you please check how the trapezoid is translated from CAD to root. Is it done as a trap or as an arbitrary8?

You can check this in CxIInfoPart.cc. If the first line of IsTrap() is commented out (return false), than it gives back traps, otherwise Arb8.

Independent how the setting is, change this line and check if now hits are produced.

Cheers,

Tobias

Page 1 of 1 ---- Generated from GSI Forum