

---

Subject: Re: change of geometry for EMC

Posted by [Stefano Spataro](#) on Thu, 23 Jul 2009 13:48:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi,

I think the gap will never be filled, because space is needed for the cables and that is the only space left on the backward part.

Comments from others working on the backward endcap are requested.

---