

---

Subject: Re: Geometry of EMC Barrel Crystal  
Posted by [Christian Hammann](#) on Fri, 18 Sep 2009 13:12:32 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi

sorry I think copied some wrong numbers from the TDR.  
0.2mm probably won't make a difference.

But I am still a little puzzled by the less than 90 deg. angle between the frontface and one of the sides of the crystal.

You can see that angle in the picture above. (The bottom of the crystal is in the plane of the x and z axis) Is that correct? that seems not to be indicated in the TDR.

Thanks for your help

Christian

---