

---

Subject: Re: Drift HV to Radiator connection

Posted by [Harald Appelshaeuser](#) on Thu, 23 Sep 2004 09:36:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Clemens,

1. indeed this shielding is a tricky thing. we fell into the same trap with the very first proto we built in hd (sorry that i didnt communicate this well enough)
2. it seems to me that this copper strip is a weak point in the design. i dont see a problem with tiny drops of epoxy to improve the stability but maybe somebody has a good idea for a more reliable solution?

Harry

---