Subject: Anode Wire Quality
Posted by Christian Lippmann on Tue, 18 May 2004 14:42:32 GMT
View Forum Message <> Reply to Message

Hi everybody,

since one is only allowed to attach three files the anode wire images are in this topic:

TW015: A bad quality wire. The gold palting has fallen of in places.

TW025: Also not very nice.

TW031: A good wire.

Here are the images. In case you can not view them (under windows) you need to save them to your disk. Then they can be viewed.

File Attachments

1) TW015-2.TIF, downloaded 1313 times
2) TW025-4.TIF, downloaded 1308 times
3) TW031-4.TIF, downloaded 1396 times