
Subject: Anode Wire Quality

Posted by [Christian Lippmann](#) on Tue, 18 May 2004 14:42:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi everybody,

since one is only allowed to attach three files the anode wire images are in this topic:

TW015: A bad quality wire. The gold palting has fallen of in places.

TW025: Also not very nice.

TW031: A good wire.

Here are the images. In case you can not view them (under windows) you need to save them to your disk. Then they can be viewed.

File Attachments

- 1) [TW015-2.TIF](#), downloaded 934 times
 - 2) [TW025-4.TIF](#), downloaded 948 times
 - 3) [TW031-4.TIF](#), downloaded 981 times
-