

---

Subject: Some Interesting Plots

Posted by [Sascha Freuen](#) on Thu, 30 Sep 2004 15:32:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Chamber L1C0#2 , before the panel with the badly glued padplane was exchanged :

Example of a chamber with good gain uniformity :

Here we have suspicion, that there is one layer of fibre mats too much :

4mm step scan in z-direction. Here one anode wire is missing- you can see clearly where :

another 4mm step scan in z-direction (3 padrows have been disconnected from ground) :